

## Colorado Restricted Dams List, as of August 20, 2013

## DIVISION 1

DAMID	Haz. Class	Dam name	Restricted Reservoir Level	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
640104		1 JULESBURG #4	GH 24 FT. FOR 90 DAYS, THEN GH 23 FT.	CONDITION OF OUTLET, EXCESSIVE SEEPAGE	24	5/2/1995	R	6964
230102		1 ANTERO	GH 18 FT.	STAB. BERM CONST. & NEW INSTR. MONITORING	18	2/4/1986	R	6500
640108		1 PREWITT	GH 28.5 FT.	NO SPWY & EXCESSIVE SEEPAGE	26.5	8/23/1990	I	2531
10115		2 BIJOU #2 DAM #1	GH 16; not > GH 15 for more than 30 days	scarping, seepage, no spillway	16	6/1/1993	C	2400
30107		1 BLACK HOLLOW	4.2 FT. SPILLWAY	INADEQUATE SPILLWAY	31	10/22/1997	I	999
30229		3 MOUNTAIN SUPPLY # 8	NO STORAGE	POOR CONDITION	0	10/3/1978	I	643
30301		2 NORTH Poudre # 4	GH 17 FT.	POOR U/S FACE, GENERAL CONDITION	17	4/17/1984	R	562
30225		3 MOUNTAIN SUPPLY # 1	10 FT. CREST	POOR CONDITION	5	11/5/1997	I	500
10419		3 D.A. LORD #4	2.0 SPILLWAY	INADEQUATE SPILLWAY	0	9/19/1980	C	400
30122		2 CURTIS LAKE	GH 10 FT.	CREST, SLOPE, EXT. SEEP. AREA BELOW D/S TOE	10	7/2/1985	I	397
30226		3 MOUNTAIN SUPPLY # 2	10 FT. CREST	POOR CONDITION	5	11/5/1997	I	300
90115		2 HARRIMAN	GH 19 FT.	EXCESSIVE SEEPAGE	19	11/12/1992	R	300
10709		3 JOLLY JOHN	NO STORAGE	SCOUR HOLE FROM OUTLET	0	10/27/2000	I	297
50206		3 KNOUTH	NO STORAGE	NEVER COMPLETED DAM	0	12/24/1985	I	204
75311		1 SMITH	2.0 SPILLWAY	SEEPAGE		6/7/2010	R	200
30129		2 EATON - LAW	6 Feet below Dam Crest	Excessive Seepage		8/26/2011	I	150
50304		3 SWEDE	Zero Storage Restriction	PIPING OF EMBANKMENT ALONG OULLET	0	9/7/2012	I	151
10104		3 ADAMS & BUNKER #3	6.0 CREST	INADEQUATE FREEBOARD, SEEPAGE	0	5/22/1975	C	150
30128		3 DRY CREEK	GH 11.5 FT.	OUTLET DETERIORATION, SEEPAGE, INAD SW	11.5	1/17/1996	R	150
30201		2 NORTH GRAY	GH 11 OR 3 FEET BELOW SPILLWAY CREST	DETERIORATED SPILLWAY PIPE & INOPERABLE OUTLET	11	6/14/2011	I	120
30227		3 MOUNTAIN SUPPLY # 6	3.0 CREST	NO SPILLWAY		10/19/2000	C	120
60314		3 HODGSON-HARRIS	ZERO STORAGE	CONTINUAL DETERIORATION	0	7/8/2009	R	119
80306		3 WAKEMAN	NO STORAGE	SPILLWAY EROSION		10/17/1994	I	110
10612		3 NO NAME 1-1 #1	10 FT. CREST	SCOUR OF D/S SLOPE DUE TO FAILURE OF OUTLET		11/2/2000	I	100
30138		N GRAY #3	NO STORAGE	SINKHOLE OVER OUTLET	0	5/27/1997	I	100
30220		3 MATTINGLY	2.0 FT. SPILLWAY	EROSION/3-5 FT. SCARP ON U/S FACE		10/23/1997	I	99
30309		3 PARK CREEK #2	Zero Storage Restriction	Inoperable Outlet - Dam Breached by Owner	0	1/23/2009	I	97
80327		1 SKEEL	5.0 Feet Below Spillway Crest	Poor Condition, seepage		11/2/2007	R	75
480101		3 JOHNSON	4.0 CREST(3.0 CREST IRR. SEASON)	EROS. ON U/S FACE, IMPROPER FB., SEEP/D/S TOE	0	7/18/1994	C	68
80321		4 QUICK	NO STORAGE	NO SPILLWAY, INOPERABLE OUTLET	0	10/22/1987	I	64
10138		3 DOVER	10.0 FT. CREST	POOR CONDITION		6/27/1986	I	60
20322		2 SIGNAL #1	5.0 CREST	CONCENTRATED SPG AREAS & QUESTIONABLE COND OF OUTLET	0	6/21/1993	R	60
50212		3 LITTLE GEM	10.0 CREST	EROSION ON U/S SLOPE & CRST, TREES ON U/S SLOPE	0	10/11/1985	I	60
10716		3 HOWARDS LAKE	3.0 FT. SPILLWAY	EROSION OF DAM AND CREST		6/3/1998	I	50
20411		2 NISSEN #2	2.0 FEET BELOW SPILLWAY CREST	RELAXED TO ALLOW WATER STORAGE THROUGH WINTER		10/1/2010	R	50
80101		3 ALLIS	15.0 CREST	SLOUGHING, SEEPAGE	0	8/25/1992	R	50
30108		3 BOX ELDER #2	3.0 FT. SPILLWAY	EXCESSIVE SEEPAGE	6.5	8/8/1989	I	49
30214		3 LAW, JOHN	3.0 CREST	INADEQUATE SPILLWAY AND FREEBOARD	11	6/22/1987	C	45
60307		3 LAKE MANCHESTER	2' below spillway	Poor condition of dam and lack of maintenance		8/8/2012	I	40
80110		4 CANTRILL	NO STORAGE	NO SPILLWAY, INOPERABLE OUTLET	0	10/22/1987	I	37
50101		2 AKERS & TARR	7.0 CREST OCT. 1 - APRIL 1	SLIDE ON D/S SLOPE, SPGE. IN AREA OF ABAND OTL	0	3/23/1989	R	34
30512		3 RIST CANYON	3.0 CREST	SEEPAGE, INADEQUATE SPILLWAY	0	4/19/1983	I	33
20333		3 THOMPSON	5.0 CREST	INADEQUATE FREEBOARD, GENERALLY POOR CONDITION	0	10/7/1987	R	30
80105		3 BAIRD #1	7.0 CREST	SEVERE BEAVER ACTIVITY, PLUGGED OUTLET	0	1/8/1990	I	25
80422		3 RAINBOW FALLS #5	9.0 CREST	INADEQUATE SPILLWAY	0	9/11/1985	I	25
90204		1 WILLOW SPRINGS #1	2.0 feet below spillway	Return to previously restricted storage	16	9/28/2012	R	16
70126		2 DEWEY NO. 1	3.0 CREST(NW)	POOR CONDITION	0	11/19/1990	I	15
650121		3 DUCK	4.0 SPILLWAY	NARROW CREST, STEEP SLOPES	0	3/23/1987	I	15

Colorado Restricted Dams List, as of August 20, 2013

650123.	3	HANSHAW	5.0 CREST	seepage, slide, overall poor	0	7/7/1987	I	12
80424	3	GERLITS	NO STORAGE	DAM PARTIALLY BREACHED DUE TO OVERTOPPING.	0	11/13/1984	I	10
800139	3	GREEN VALLEY RETENTION	Zero Storage	Scarp at Outlet, PoorCondition Inoperable Gate	0	1/28/2008	I	10
80445	3	FREDERICKSON LAKE	5 FEET BELOW DAM CREST	Continual Deterioration of Dam and Structures	0	4/6/2009	R	5
230312	3	WIND	5.5 CREST	SATURATED D/S SLOPE	0	9/20/1985	C	3
10132	3	LINDIES LAKE	3 ft below top of headwall	provide minimum freeboard		5/6/1998	R	0
10506	1	RIVERSIDE	GH 33.55 FT.	no spillway; 33.55 is max decree	33.5	5/9/1984	I	0
20113	3	CARLIN	5.0 CREST	NO SPILLWAY	0	7/29/1986	C	0
20115	3	LOWER CHURCH LAKE	3.0 FT CREST	INADEQUATE SPILLWAY		6/22/1999	I	0
45234	3	IDE AND STARBIRD #1	3.0 CREST	POOR MN, ERODED U/S FACE, QUES. SPILLWAY	0	7/3/1985	I	0
50132	3	HIGHLAND	3.0 BELOW TOP OF CONCRETE WALL AT OUTLET	NO SPILLWAY	0	11/26/1990	R	0
50308	2	UNION	GH 28.0	spillway design based on GH=28.0	28	12/6/1977	C	0
20119	3	COLE	Converted to below grade flood control strct.	Original dam removed for housing development		8/16/2013	L	
20314	3	NORTH STAR	5.0 BELOW DAM CREST	SINKHOLE ON DOWNSTREAM SLOPE		2/11/2003	R	
20615	3	HAVANA STREET DAM	Dam rebuilt as flood control structure	Dam has converted to a flood control structure		8/16/2013	L	
640212	1	JULESBURG #1	GH 24 FOR 90 DAYS THEN GH 23	EXCESSIVE SEEPAGE	24	5/2/1995	I	
640213	1	JULESBURG #1A	GH 24 FOR 90 DAYS THEN GH 23	EXCESSIVE SEEPAGE	24	5/2/1995	I	
640214	1	JULESBURG #2	GH 24 FOR 90 DAYS THEN GH 23	EXCESSIVE SEEPAGE	24	5/2/1995	I	
640215	1	JULESBURG #3	GH 24 FOR 90 DAYS THEN GH 23	EXCESSIVE SEEPAGE	24	5/2/1995	I	

Volume Lost to Restrictions Division 1 25634 AF

TOTAL NUMBER OF DAMS AFFECTED:

67 DAMS

DIVISION 2

DAMID	Haz. Class	Dam name	Restricted Reservoir Level	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
670236		1 TWO BUTTES	GH 32 FT., ~23 ft below the dam crest	Increased surveillance, spillway widening	32	8/19/2013	R	10151
180207		3 SEVEN LAKES	7.0 CREST	DILAPIDATED CONDITION OF DAM	0	5/6/1987	I	1200
170118		3 CUDAHY #1	5.0 FT. BELOW DAM CREST	INADEQUATE FREEBOARD AND INOPERABLE OUTLET		7/15/1985	I	900
170219		3 SWINK #5	5.0 CREST	IN DISREPAIR, ABANDONED	0	4/24/1986	I	750
100218		2 NICHOLS	Zero Storage until projects planned for 2014	Known Spillway Inadequacy for 35 yrs	0	1/22/2013	I	655
170220		3 SWINK #6	5.0 CREST	IN DISREPAIR, ABANDONED	0	4/24/1986	I	650
170218		3 SWINK #2	5.0 CREST	IN DISREPAIR, ABANDONED	0	4/24/1986	I	600
170217		3 SWINK #1	5.0 CREST	IN DISREPAIR, ABANDONED	0	4/24/1986	I	500
170222		3 TIMPAS #3	10.0 CREST	IN DISREPAIR, ABANDONED	0	4/21/1986	I	500
190116		1 NORTH LAKE	GH 60 FEET OR 5 FEET BELOW SPILLWAY CREST	HIGH PIEZOMETRIC PRESSURES AT DOWNSTREAM TOE	60	6/14/2011	I	500
100217		2 NORTHFIELD	Zero Storage, project planned for 2014	Known spillway inadequacy for 35 yrs	0	1/22/2013	I	276
180206		2 APISHAPA	22.0 CREST	SPILLWAY, OUTLET SILTED IN	0	2/18/1994	I	260
100402		2 VALLEY NO. 2	NO STORAGE	INOPERABLE OUTLET, OBSTRUCTED SPILLWAY	0	9/21/2000	C	185
170233		2 CRYSTAL LAKE	ZERO STORAGE RESTRICTION	EXTENSIVE SEEPAGE & DAM OVERGROWN W/ TREES	0	8/6/2012	I	109
160135		4 CLARK #1	8.0 CREST	ERODED UPSTREAM SLOPE	0	2/16/1994	R	80
100309		3 VALLEY NO. 1	15.0 CREST	INOPERABLE OUTLET & BLOCKED SPILLWAY	0	12/27/1984	I	50
160115		3 MC KINLEY CLAY	RESTR. TO 4' BELOW SPILL. CREST; 9'	SPILL. OBSTR., CORR. CMP COND.& WAVE BELOW DAM SCARP U/S		11/10/2011	I	40.6
100459		1 STRATTON	Gage Height 10 Feet	Outlet Not Modified to Allow No Storage	10	1/28/2008	I	32
160411		2 LA VETA LAKE NORTH	2.5 FEET BELOW SPILLWAY CREST	SEEPAGE AND CONDITION OF OUTLET WORKS		3/4/2011	I	25
120240		3 GILLETT RESERVOIR	ZERO STORAGE, MAINTAIN BREACH	BREACHED DAM	0	11/18/2006	I	12
160119		3 SHARPS ORCHARD	7 FEET BELOW THE DAM CREST	SEVERE EROSION OF U/S SLOPE & DAMAGED OUTLET		5/1/1972	I	
170137		3 HORSE CREEK AND BLACK DI	5-ft below the lowest point of the dam crest	Poor Condition of the Dam		4/24/1986	I	

Volume Lost to Restrictions Division 2 17475.6 AF

TOTAL NUMBER OF DAMS AFFECTED:

22 DAMS

DIVISION 3

Colorado Restricted Dams List, as of August 20, 2013

DAMID	Haz.	Dam name	Restricted	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
200110		1 CONTINENTAL	GH 64.5	LEAKAGE	64.5	8/1/1995	I	7679
210102		1 TERRACE	7.0 SPILLWAY	DETERIORATED SPILLWAY	117	7/18/1984	I	2000
200102		1 BEAVER PARK	20 FEET BELOW SPILLWAY CREST	SINKHOLE LEFT ABUTMENT AREA	62.3	5/7/2010	I	1700
260101		3 SAGUACHE	Zero storage	General neglect, inoperable U/S gate	0	6/28/2004	I	450
240101		3 EASTDALE #1	1.3 feet below spillway crest	Erosion of upstream slope	23	7/1/2004	I	420
350109		2 UPPER ZAPATA LAKE	0.5-ft above the gated outlet pipe invert	Seepage at d/s toe and saturation of hillside		8/18/2010	I	6
	<b>Class</b>	<b>Reservoir Level</b>	<b>ht.</b>	<b>Date</b>	<b>Type</b>	<b>Lost</b>		
<b>Volume Lost to Restrictions</b>	<b>Division 3</b>		12255 AF	<b>TOTAL NUMBER OF DAMS AFFECTED:</b>		<b>6 DAMS</b>		

**DIVISION 4**

DAMID	Haz.	Dam name	Restricted	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
400538		1 WEST #1	Zero storage	Severe deterioration of the outlet pipe.	0	6/6/2013	I	454
400608		2 YOUNGS CREEK #1 & 2	Gage height 25, 10 ft below spillway	Additional analysis and spot repairs	25	2/25/2013	R	407
420135		3 REEDER	Zero Storage	EXTENSIVE SEEPAGE, SINKHOLES AND DISREPAIR	0	12/14/2005	R	299
400122		3 BONITA	zero-storage	Leaking outlet joint just DS of upstream valve	0	3/27/2013	I	290
420120		2 GRAND MESA #1	5 FEET BELOW SPILLWAY	EMBANKMENT REPAIR AND SPILLWAY ENLARGED	15	9/11/2009	R	180
400522		3 TODD	10.0 CREST	6FT ELEVATION DIFF ALONG CREST WITH NO SPILLWAY	0	10/19/1984	I	112
400332		3 LEON PARK	Zero Storage	Sloughing U/S Slope & Deteriorated Outlet Work	0	8/9/2010	I	110
600105		3 BLUE LAKE #1	5.0 FEET SPILLWAY	POOR CONDITION		11/21/2001	I	100
630103		3 BURG	ZERO STORAGE	DAMAGED OUTLET CONTROLS		9/30/2003	I	91
400404		3 LONE CABIN	13 feet below dam crest	Additional Monitoring in place	17	2/25/2013	R	90
410201		3 COFFEY RESERVOIR	NO STORAGE	GENERAL POOR CONDITION, CONST. WO/APP. PLANS	0	7/21/1988	I	90
400524		3 TRIO	8.0 SPILLWAY	SLIDE ON DOWNSTREAM SLOPE	14	1/11/1989	J	75
630108		3 CASEMENT	2' below existing spillway crest	Inadequate freeboard		8/17/2009	I	42.2
400419		3 OASIS	3 FEET BELOW NORMAL WATER SURFACE	UNCONTROLLED SEEPAGE		9/30/2003	I	40
600126		3 CUSHMAN	6.0 CREST	OUTLET-INOP. SPWY-INAD. EMB. SEEPS	0	7/29/1975	I	36
400219		3 DON MEEK #1	7-ft below the spillway crest	Beaver activity, inoperable outlet gate		8/25/2004	J	23
400208		3 COLE #5	1.1 FT BELOW EMERGENCY SPILLWAY CREST, GH 11	ENLARGED RESERVOIR WITHOUT SEO APPROVAL	16.4	10/2/2008	J	19.1
400212		3 CYPHER #1	4.0 BELOW EMERGENCY SPILLWAY CREST	STUDY DAM UNSTABLE AT FULL RESERVOIR		4/26/2010	R	18
400705		3 WEBSTER #1	NO STORAGE	POORLY CONSTRUCTED	0	5/6/1987	C	15
400707		3 WEBSTER #3	NO STORAGE	POORLY CONSTRUCTED	0	5/6/1987	C	15
400712		3 GLORIA	3 FEET BELOW DAM CREST	NO SPILLWAY, EXCESSIVE SEEPAGE, NO FREEBOARD		6/7/2010	I	6
400330		3 KNOX	FULL STORAGE FROM 4/1 TO 8/15 IF MONITORED	EXCESSIVE SEEPAGE AT TOE AND ON EMBANKMENT	17	1/8/1988	R	0
400405		3 LONE STAR #1	30.0 CREST	CRACKS ON CREST, UNAPPROVED PLANS, POOR CONSTR	0	7/31/1996	R	0
400619		3 LONE STAR #2	10.0 CREST	CONSTRUCTION WITHOUT APPROVED PLANS & SPECS	0	6/2/1988	C	0
400706		3 WEBSTER #2	ZERO STORAGE			5/6/1987	I	
<b>Volume Lost to Restrictions</b>	<b>Division 4</b>		2512.3 AF	<b>TOTAL NUMBER OF DAMS AFFECTED:</b>		<b>25 DAMS</b>		

**DIVISION 5**

DAMID	Haz.	Dam name	Restricted	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
	<b>Class</b>		<b>Reservoir Level</b>					
510114		2 LITTLE KING RANCH	GAGE HEIGHT 25 FEET	SINKHOLE AND EXCESSIVE SEEPAGE	25	2/8/2010	R	900
380219		1 POLARIS	16.5 FT BELOW DAM CREST	INADEQ SPWY & FB, BASIN SEEP, POOR FOUNDATION	4	11/1/2007	R	770
720136		3 HAWXHURST	Zero Gage Height, No Storage	Hole in Outlet Conduit and Sinkholes	0	8/21/2006	R	207
720115		1 BULL CREEK #4	6 feet below emergency spillway crest	Severely Eroded Spillway and Embankment	18	10/18/2012	I	184
530119		3 KELLY	3.5 FT BELOW SERVICE SPILLWAY	INCREASE IN SEEPAGE	96.5	6/29/2006	R	84

Colorado Restricted Dams List, as of August 20, 2013

510103	3	COTTONWOOD	Zero Storage	Spillway back cutting, inoperable outlet	0	7/1/2013	I	71
720203	3	KENDALL	Zero Storage Restriction	Wave Erosion, Dam Instability & Blocked Spill	0	8/27/2007	I	61
380121	3	RALSTON #1	ZERO STORAGE	POOR CONDITION OF OUTLET CONDUIT	0	11/17/2009	I	60
500126	3	MILK CREEK	15.0 CREST (AUG 1 THRU MAY 1)	EXCESSIVE LEAKAGE	0	5/10/1991	R	56
360117	1	OLD DILLON	ZERO STORAGE	CONTINUAL DETERIORATION OF DAM	0	7/17/2008	I	46
530114	3	HOLDEN	Zero Gage Height, No Storage	Seepage above serv Spwy on Downstream Slope	0	8/21/2006	R	31
380231	2	VALANA K RESERVOIR NO. 1	ZERO STRORAGE	UNAPPROVED SPILLWAY AND POOR CONDITION	0	11/13/2008	I	19
380204	2	CHRISTENSON	Zero Storage	Sloughing of Downstream Slope	0	7/6/2005	I	11
450128	3	R-4 RODREICK RESERVOIR	4 FEET BELOW DAM CREST	ILLEGALLY CONSTRUCTE AND NO SPILLWAY		5/26/2009	I	10
360135	2	BILLS RANCH LAKE	ZERO STORAGE	SINKHOLES, POOR DAM COND.		11/1/2011	R	7
450131	3	RIEGER POND	4.5 FEET BELOW DAM CREST	IILLEGALLY CONSTRUCTED AND NO SPILLWAY		5/26/2009	I	7
500113	2	MATHESON	FULL STOR IN SPRING. DRAIN TO GH 30 BY 9/1	MONITORING DEVISE INSTALLED	30	10/30/2002	R	0

Volume Lost to Restrictions

Division 5

2524 AF

TOTAL NUMBER OF DAMS AFFECTED:

17 DAMS

**DIVISON 6**

DAMID	Haz. Class	Dam name	Restricted Reservoir Level	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
570114	3	LAKE EMRICH	15 FEET BELOW CREST	SLIDES ON DOWNSTREAM SLOPE	0	8/30/1988	C	330
440120	3	DRESCHER	8.0 SPILLWAY	SEEPAGE & INSTABILITY	8	8/1/1988	R	159
580115	3	LAKE WINDEMERE	Zero Storage	Rusted Outlet Pipe, inoperable outlet valve	0	7/1/2013	I	137
440213	3	FLAT TOP	10 FEET BELOW DAM CREST	CONTINUAL DETERIORATION OF DAM		3/2/2009	R	75
430205	3	BAXTER	Breach or hire an engineer	Seepage , erosion, crest settling, lack of FB		3/7/2006	R	50
470310	4	UPPER THREE MILE #1	No Storage, keep gate open.	Illegal Construction	0	6/29/2006	I	47
570124	3	NOFSTGER-ZEIGLER	9 FEET BELOW DAM CREST	POOR CONDITION OF DAM AND SEEPAGE		7/14/2009	I	40
440208	3	SHAFFER	ZERO STORAGE	INOPERABLE OUTLET AND POOR CONDITION OF DAM		1/15/2009	I	31
570128	3	SEATON	Zero Storage Restriction	Slide on Downstream Slope & Inoperable Outlet	0	8/27/2007	I	21
430212	3	WILSON #3	3.0 SPILLWAY	INOPERABLE OUTLET, INAD SPWY	3	9/30/1989	I	10
470308	3	LARSON #1	ZERO STORAGE	EROSION DAMAGE IN SPILLWAY & POOR MAINTENANCE		2/8/2010	I	8

Volume Lost to Restrictions

Division 6

908 AF

TOTAL NUMBER OF DAMS AFFECTED:

11 DAMS

**DIVISON 7**

DAMID	Haz. Class	Dam name	Restricted Reservoir Level	Reason for Restriction	Gage ht.	Action Date	Action Type	Volume Lost
320107	1	TOTTEN	5 FEET BELOW EMERGENCY SPILLWAY	CRACKING OF EMBANKMENT CREST	8.95	10/7/2009	I	1000
340203	1	SUMMIT - MAIN DAM	NOT TO EXCEED 1.1 FT BELOW SPILL FOR >	EXCESSIVE SEEPAGE 3 WKS	23.6	6/3/1998	R	400
320106	3	GRIMES	Zero-Storage Restriction	Inoperable Outlet, Excessive outlet leakage,	0	5/2/2012	I	75
300140	3	JOHNSON #2	11' Below Crest - Open Outlet	Spillway Obstruction; General Neglect		11/4/2009	I	54
320202	3	E. G. MERRITT	Zero Storage	Deteriorated Outlet Conduit, Inoperable Outlet		6/13/2006	I	41
340106	3	HURST	NO STORAGE	OUTLET FAILURE	0	3/29/1999	I	35
340119	3	J. O. SPENCER	NO STORAGE	INOPERABLE OUTLET	0	5/8/2000	I	16
300150	3	BONNER POND	Return to full storage	Made additional repairs to lining		6/28/2013	R	12
300144	3	UPPER RAILROAD	5 Feet below Dam Crest	Inadequate Spillway& Unstable Downstream Slope		9/8/2005	I	4

Volume Lost to Restrictions

Division 7

1637

AF

TOTAL NUMBER OF DAMS AFFECTED:

9

DAMS

TOTAL # of Dams and Volume Lost

155

62947

Restriction Action Coding: I = first Initiated, R = Revised, C = Changed, L = Lifted