BASEMENT FLOOR	
BAGEMENTTEOOK	
South Entrance Basement	
Picture # 1	South West Wall
Picture # 2	South East Wall to the left of room 091
Picture # 3	South East Wall to the left of room 091
Picture # 4	South East Wall corner by men's restroom #098
Picture # 5	South East Wall out side room 0100
Picture # 6	South East Pillar outside rotunda to the east
Picture # 7	South East Pillar just outside rotunda
Picture # 8	South East Wall to the right of north elevator
Picture # 9	East exit of rotunda
Picture # 10	East wall by south elevator door
Picture # 11	Left side corner by north elevator
Picture # 12	Left side of elevator door
North Entrance Basement	
Picture # 13	Left side of door at room 019
Picture # 14	Right side of door at room 019
Picture # 15	Pillar across from room 019
Picture # 16	Corner to the left of room 019
Picture # 17	
Picture # 17	Corner to the left of room 039
FIRST FLOOR	
South Entrance First Floor	
Picture # 18	Room 127 office enter door left side
Picture # 19	Stairwell area east side right side of door
Picture # 20	Pillar just right of the stairwell floor needs repair
Picture # 21	Third pillar from south entrance east door
Picture # 22	Area around the corner to the west of the south elevator
Picture # 23	Corner to the right of the south elevator
East Entrance First Floor	
Picture # 24	Right side of south elevator door
Picture # 25	North wall by east door
Picture # 26	Right side of door room 114

Picture # 27	Corner to the left of the north elevator
North Entrance First Floor	
Picture # 28	Right of office 111
Picture # 29	Left of office door 111
Picture # 30	Damage to pillar in front of men's restroom
Picture # 31	Damage to pillar out side of men's restroom to the right
Picture # 32	Second pillar from north door on the east side
Picture # 33	Last pillar left side by rotunda north entrance
West Entrance First Floor	
Picture # 34	End of the hall to the left of the Governors personal office entrance
Picture # 35	North east area of rotunda by display
Second Floor South Side	
Picture # 36	Hallway to the left of room 262
Picture # 37	Beneath brass rail across from rotunda
Picture # 38	Beneath brass rail across from house south entrance
Picture # 39	Damage is to the left of room 246 in hallway
Picture # 40	Damage is out side of room 246
Picture # 41	Damage is to the bottom of brass rail across from room 243
Picture # 42	Damage is to the right of the south entrance to the rotunda
Picture # 43	Damage is to the right of the south entrance to the rotunda
Second Floor North Side	
Picture # 44	Damage is to the right of the north entrance to the rotunda
Picture # 45	Damage is to the left of the northwest entrance to the sperm court
Picture # 46	Damage is to the left of room 223
Picture # 47	Damage is to the right of 223
Picture # 48	Marble is not secured to wall (Marble has plumbing running through it.)
Picture # 49	Beneath brass rail across from room 206
Picture # 50	Damage is to the right of room 206
Picture # 51	Damage is to the left of the north entrance of the Senate chambers
Picture # 52	Damage is to the right inside north entrance of the Senate chambers

Third Floor South Side	
Picture # 53	Damage is to the left of the southwest entrance to the house gallery
Picture # 54	Damage is to the left of the southwest entrance to the house gallery upper rail
Picture # 55	Damage is to the marble on northwest corner of the brass railing
Picture # 56	Damage is to the marble on northeast corner of the brass railing
Picture # 57	Damage is to the marble on southeast wall of the Senate gallery
Picture # 58	Damage is to the marble on corner to the left of room 340
Picture # 59	Damage is to the marble on southeast wall of the Senate gallery
Picture # 60	Damage is to the left of the rotunda south entrance
Picture # 61	Damage is to the marble out side of room 355
Picture # 62	Damage is to the left of the rotunda north entrance
Picture # 63	Damage is to the left of room 301
Picture # 64	Damage is to the left of room 312
Picture # 65	Damage is to the left of the north east stairwell glass door
Picture # 66	Retake of #65

. .