

Shepherd, Lance

From: Corson, Dan
Sent: Thursday, May 06, 2010 12:45 PM
To: Shepherd, Lance
Subject: RE: Capitol Exterior Stairs - Proposed Bollards - North & South

Dear Lance:

Thank you for consulting with our office regarding replacing the fiberglass planters with bollards. We recommend that this change will result in no adverse effect to the State Capitol site.

Please let me know if you require additional information.


Sincerely,

Dan W. Corson
Intergovernmental Services Director
Office of Archaeology and Historic Preservation
History Colorado [Colorado Historical Society]
Civic Center Plaza
1560 Broadway, Suite 400
Denver, Colorado 80202
(303) 866-2673
www.coloradohistory-oahp.org


From: Shepherd, Lance
Sent: Wednesday, May 05, 2010 2:13 PM
To: Corson, Dan
Subject: FW: Capitol Exterior Stairs - Proposed Bollards - North & South

Dan

We met with Joseph Saldibar last week to review replacing the fiberglass planters in front of the North and South steps of the capitol. The planters have been in place 7 years and are failing. We would like to replace them with the same bollards we used at the Legislative Services Building. Please review and let me know if you have any objections with replacing the planters with bollards.
Thanks
Lance








Lance Shepherd, Architect, LEED AP

5/21/2010



DATE 12-15-03
 REVISION
 DATE 4-29-10

REPAIR EXTERIOR STAIRS - STATE CAPITOL
 1201 EAST CALPAX AVENUE - DENVER, COLORADO